



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

Internal 2009  
S/007/0037

0001

**Inspection Report**  
**Minerals Regulatory Program**  
November 18, 2009

Reviewed:

<b>Mine Name:</b> Martin	<b>Permit Number:</b> S/007/0037
<b>Operator Name:</b>	<b>Inspection Date:</b> November 18, 2009
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 9:15- 9:40 AM
<b>Other Participants:</b> Chris Conrad (BLM)	<b>Mine Status:</b> SUS

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

This was a routine inspection.

**Inspection Summary:**

The site was stable and will qualify for release once the seeding has been completed.

- (1) The Division does not have a bond on the site. The Division will retire the permit if the Operator seeds the site by December 30, 2009.
- (2) The Division and the BLM found the site to be safe.
- (3) The Division did not see any signs of erosion.

**Conclusions and Recommendations:**

The Division should verify if the Operator did the required seeding. If seeding is accomplished by December 30, 2009, then the Division should retire the permit.

**Inspector's Signature**

(whw):pb

0001



Inspection Date: November 18, 2009  
Page 2 of 3  
S/007/0037

cc: (OPERATOR)

[Christopher.Conrad@blm.gov](mailto:Christopher.Conrad@blm.gov)

P:\GROUPS\MINERALS\WP\M007-Carbon\S0070037-Martin\inspections\Insp\_11182009.doc





Above, area that had rocks removed. Below area that had been mined and earthwork completed.

